


FIG. 1

2/11

FIGURE 2



3/11

FIGURE 3





FIGURE 4



5/11

General Syntax: <!-- get:functionname attribute1=values1 attribute2=values2 ... -->

200

202

204

204

FIG. 5

<!--get:getObject table=<R start_addr+9 length>-->

210


212

214

214

FIG. 6

6/11



220

FIG. 7

7/11

```
<html>
<head>
<title> CPU374 PLC Mode </title>
</head>
<body>
<table border="1" >
  <tr>
    <td ><b>CPU374 PLC Mode Display</b></td>
  </tr>
  <tr>
    <td >PIC Mode:</td>
    <td ><input type="checkbox" value="1" /> gef:plcMode </td>
  </tr>
</table>
</body>
</html>
```

FIG. 8

230

```
<html>
<head>
<title> CPU374 PLC Mode </title>
</head>
<body>
<table border="1" >
  <tr>
    <td ><b>CPU374 PLC Mode Display</b></td>
  </tr>
  <tr>
    <td >PIC Mode:</td>
    <td ><input type="checkbox" value="1" /> Rnn I/O Enabled </td>
  </tr>
</table>
</body>
</html>
```

FIG. 9

240

8/11

```
<html>
<head>
<title>CPU374 PLC Mode </title>
</head>
<body>
<script>
<!-- hide me
var PLC_mode = "<!-- gsf:plcMode -->"
// stop hiding -->
</script>
<table border="1" >
  <tr>
    <td >CPU374 PLC Mode Display</td>
  </tr>
  <tr>
    <td >PLC Mode</td>
  </tr>
</table>
<script>
<!-- hide me
document.write("<td>");
document.write(PLC_mode);
document.write("</td>");
// stop hiding -->
</script>
</tr></table></body></html>
```

252

250

FIG. 10

9/11




FIGURE 11

11/01




FIGURE 12

FIGURE 13

